

The Attached Report is performed by Property Reports On Sight, LLC Certified Field Inspectors and thus should not be confused with an inspection performed by Licensed Real Estate Commission Inspectors. This report is an assessment of the condition of the property on the date shown and only the items listed in the report with notations made are reported on. Certified Field Inspectors are not licensed to check the mechanicals, plumbing, or electrical units in a home and therefore this report will not reflect any issues or functionality of those components. This report is for the use of the property manager and/or owner to see first hand the condition of the property address as shown on the report.

3/16/2013 11:21 AM

Inspector: Sal Salang

CUSTOMER NO.: KPM

St. Address: 25214 Bluma Ranch

City: Katy

ST: TX

Zip Code: 77494

Type of Inspection: Periodic Report

3/16/2013 12:05:22 PM CAM



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Exterior	Observed	NA	Futher Evaluation	Exterior Comments:
1 . Roof/Trim	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4 . Front/Back/SideDoor-back door t...
2 . Exterior Door	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14 . Other-window in backyard by pa...
3 . Walls-All Around	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Front/Back/SideDoor	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
5 . Porch/Patio/Deck	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7 . Mail Box	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
8 . Fences (Front & Rear)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9 . Driveway	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
10 . Lawn-Grass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11 . Trees/Touching House	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
12 . Shrubs and Brushes	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
13 . Pool	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
14 . Other	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

746

3/16/2013 12:05:22 PM CAM



747

3/16/2013 12:08:3 PM CAM



748

3/16/2013 12:08:29 PM CAM



749

3/16/2013 12:08:43 PM CAM



752

3/16/2013 12:09:36 PM CAM



753

3/16/2013 12:09:56 PM CAM



754

3/16/2013 12:10:3 PM CAM




755

3/16/2013 12:10:23 PM CAM



765

3/16/2013 12:12:20 PM CAM



768

3/16/2013 12:15:44 PM CAM



Slight leak when windy

Exterior Comments:

4 . Front/Back/SideDoor-back door trim on frame rotted. Pic on backyard tab.

14 . Other-window in backyard by patio door leaks slightly when rainy and windy per tenant.

Entry	Observed	NA	Futher Evaluation	Entry Comments:
1 . Visible Address	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Floors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Front Door	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Keyless Lock	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Peephole	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

769

3/16/2013 12:16:56 PM CAM




770

3/16/2013 12:17:1 PM CAM



771

3/16/2013 12:17:7 PM CAM



772

3/16/2013 12:17:14 PM CAM



Living Room	Observed	NA	Futher Evaluation	Living Room Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Light Fixture	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Ceiling Fan	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7 . Outlet/Switch Covers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

814 3/16/2013 12:28:30 PM CAM



815 3/16/2013 12:28:37 PM CAM



816 3/16/2013 12:28:49 PM CAM



817 3/16/2013 12:29:45 PM CAM



Game Room	Observed	NA	Futher Evaluation	Game Room Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Light Fixture	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Ceiling Fan	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Outlet/Switch Covers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

865 3/16/2013 12:41:25 PM CAM



866 3/16/2013 12:41:32 PM CAM



867 3/16/2013 12:41:38 PM CAM



868 3/16/2013 12:41:49 PM CAM



869

3/16/2013 12:42:0 PM CAM



871

3/16/2013 12:42:20 PM CAM



872

3/16/2013 12:42:28 PM CAM



Dining Room

- 1 . Flooring
- 2 . Walls/Paint
- 3 . Light Fixture
- 4 . Blinds/Drapes
- 5 . Windows
- 6 . Ceiling Fan
- 7 . Outlet/Switch Covers
- 8 . Other

Observed

NA

Futher Evaluation

Dining Room Comments:

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

826

3/16/2013 12:31:50 PM CAM



827

3/16/2013 12:31:55 PM CAM



828

3/16/2013 12:32:5 PM CAM



829

3/16/2013 12:32:11 PM CAM



830

3/16/2013 12:32:17 PM CAM



831

3/16/2013 12:32:24 PM CAM



Kitchen	Observed	NA	Futher Evaluation	Kitchen Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Ceiling	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Kitchen Counter/Back Splash	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7 . Sink/Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Cabinet Under Sink	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9 . Garbage Disposal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
10 . Refrigerator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11 . Range/Oven	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
12 . Dishwasher	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
13 . Oven	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
14 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

818 3/16/2013 12:30:14 PM CAM



819 3/16/2013 12:30:20 PM CAM



820 3/16/2013 12:30:26 PM CAM



821 3/16/2013 12:30:32 PM CAM



822

3/16/2013 12:30:38 PM CAM



823

3/16/2013 12:30:50 PM CAM



824

3/16/2013 12:31:2 PM CAM



825

3/16/2013 12:31:17 PM CAM



Hallway / Stairway	Observed	NA	Futher Evaluation	Hallway / Stairway Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Light Fixture	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Outlet/Switch Covers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Smoke Detector	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

832 3/16/2013 12:32:50 PM CAM



833 3/16/2013 12:33:7 PM CAM



834 3/16/2013 12:33:15 PM CAM



835 3/16/2013 12:33:23 PM CAM



836

3/16/2013 12:33:39 PM CAM



Bedroom	Observed	NA	Futher Evaluation	Bedroom Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	2 . Walls/Paint-evidence of water l...
2 . Walls/Paint	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
3 . Light Fixture	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Ceiling Fan	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7 . Outlet/Switch Covers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Smoke Detector	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

792

3/16/2013 12:22:39 PM CAM



Paint bubbling

793

3/16/2013 12:23:7 PM CAM



Paint bubbling

794

3/16/2013 12:23:12 PM CAM



795

3/16/2013 12:23:40 PM CAM



796

3/16/2013 12:23:46 PM CAM



797

3/16/2013 12:23:54 PM CAM




798

3/16/2013 12:24:1 PM CAM



799

3/16/2013 12:24:6 PM CAM



800

3/16/2013 12:24:19 PM CAM



Bedroom Comments:


2 . Walls/Paint-evidence of water leak on a wall due to paint peeling.

Bedroom 2	Observed	NA	Futher Evaluation	Bedroom 2 Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Light Fixture	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Ceiling Fan	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Outlet/Switch Covers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Smoke Detector	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

837 3/16/2013 12:34:7 PM CAM



838 3/16/2013 12:34:19 PM CAM



839 3/16/2013 12:34:26 PM CAM



840 3/16/2013 12:34:33 PM CAM



841

3/16/2013 12:34:45 PM CAM



842

3/16/2013 12:34:55 PM CAM



Bedroom 3

Observed

NA

Futher Evaluation

Bedroom 3 Comments:

1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3 . Light Fixture	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5 . Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6 . Ceiling Fan	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7 . Outlet/Switch Covers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8 . Smoke Detector	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

844

3/16/2013 12:36:7 PM CAM




845

3/16/2013 12:36:15 PM CAM



846

3/16/2013 12:36:27 PM CAM



847

3/16/2013 12:36:40 PM CAM



848

3/16/2013 12:36:50 PM CAM



849

3/16/2013 12:37:4 PM CAM



Bedroom 4	Observed	NA	Futher Evaluation	Bedroom 4 Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Light Fixture	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Ceiling Fan	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Outlet/Switch Covers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Smoke Detector	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

850 3/16/2013 12:37:41 PM CAM



851 3/16/2013 12:37:48 PM CAM



852 3/16/2013 12:37:58 PM CAM



853 3/16/2013 12:38:5 PM CAM



854

3/16/2013 12:38:16 PM CAM



855

3/16/2013 12:38:24 PM CAM



856

3/16/2013 12:38:36 PM CAM



Bathroom	Observed	NA	Futher Evaluation	Bathroom Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Ceiling/Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Blinds/Drapes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6 . Window	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7 . Sink/Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Cabinet Under Sink	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9 . Shower Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
10 . Tub/Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11 . Commode	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
12 . Towel Racks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
13 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

801 3/16/2013 12:25:39 PM CAM



802 3/16/2013 12:25:48 PM CAM



803 3/16/2013 12:26:0 PM CAM



804 3/16/2013 12:26:9 PM CAM



805

3/16/2013 12:26:14 PM CAM



806

3/16/2013 12:26:20 PM CAM



807

3/16/2013 12:26:32 PM CAM



808

3/16/2013 12:26:37 PM CAM




809

3/16/2013 12:26:46 PM CAM



810

3/16/2013 12:26:52 PM CAM



811

3/16/2013 12:26:59 PM CAM



812

3/16/2013 12:27:7 PM CAM



813

3/16/2013 12:27:16 PM CAM




Powder room	Observed	NA	Futher Evaluation	Powder room Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Ceiling/Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Blinds/Drapes	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6 . Window	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Sink/Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Cabinet Under Sink	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
9 . Shower Faucet	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
10 . Tub/Faucet	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
11 . Commode	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
12 . Towel Racks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
13 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

773 3/16/2013 12:17:58 PM CAM



774 3/16/2013 12:18:4 PM CAM



775 3/16/2013 12:18:10 PM CAM



776 3/16/2013 12:18:18 PM CAM



777

3/16/2013 12:18:25 PM CAM



778

3/16/2013 12:18:30 PM CAM



Bathroom 2	Observed	NA	Futher Evaluation	Bathroom 2 Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Ceiling/Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Blinds/Drapes	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6 . Window	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Sink/Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Cabinet Under Sink	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9 . Shower Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
10 . Tub/Faucet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
11 . Commode	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
12 . Towel Racks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
13 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

857 3/16/2013 12:39:29 PM CAM



858 3/16/2013 12:39:34 PM CAM



859 3/16/2013 12:39:48 PM CAM



860 3/16/2013 12:39:58 PM CAM



861

3/16/2013 12:40:8 PM CAM



862

3/16/2013 12:40:14 PM CAM



863

3/16/2013 12:40:22 PM CAM



864

3/16/2013 12:40:27 PM CAM



Utility Room	Observed	NA	Futher Evaluation	Utility Room Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Washer Connection	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Blinds/Drapes	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6 . Window	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

779 3/16/2013 12:19:3 PM CAM



780 3/16/2013 12:19:14 PM CAM



781 3/16/2013 12:19:25 PM CAM



782 3/16/2013 12:19:32 PM CAM



783

3/16/2013 12:19:42 PM CAM



784

3/16/2013 12:19:50 PM CAM



785

3/16/2013 12:19:59 PM CAM



786

3/16/2013 12:20:7 PM CAM



Garage	Observed	NA	Futher Evaluation	Garage Comments:
1 . Flooring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Walls/Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Light Fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Blinds/Drapes	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5 . Window	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6 . Garage Door	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

787 3/16/2013 12:20:40 PM CAM



788 3/16/2013 12:20:54 PM CAM



789 3/16/2013 12:21:0 PM CAM



790 3/16/2013 12:21:22 PM CAM



791

3/16/2013 12:21:30 PM CAM



Miscellaneous	Observed	NA	Futher Evaluation	Miscellaneous Comments:
1 . Water Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . AC Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Satellite Dish	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Missing/Tom Screens	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5 . Trip Hazards	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6 . Drainage Issues	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Smoke Detector	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

750

3/16/2013 12:09:5 PM CAM



751

3/16/2013 12:09:25 PM CAM



843

3/16/2013 12:35:27 PM CAM



873

3/16/2013 12:45:5 PM CAM



Hot water heater in attic

Backyard	Observed	NA	Futher Evaluation	Backyard Comments:
1 . Yard / Grass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2 . Fence	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3 . Air Conditioner	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4 . Patio / Porch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5 . Pet Evidence	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6 . Tobacco Remains	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7 . Insurance Risks	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
8 . Pool	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
9 . Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

756

3/16/2013 12:10:33 PM CAM



757

3/16/2013 12:10:40 PM CAM



758

3/16/2013 12:10:46 PM CAM



759

3/16/2013 12:10:57 PM CAM



760

3/16/2013 12:11:4 PM CAM



761

3/16/2013 12:11:11 PM CAM



762

3/16/2013 12:11:21 PM CAM



Trim rotted

763

3/16/2013 12:11:33 PM CAM



Backyard door

764

3/16/2013 12:12:0 PM CAM



766

3/16/2013 12:15:4 PM CAM



767

3/16/2013 12:15:20 PM CAM

